

REPORT SUMMARY

CLAIM INFORMATION

Owner	██████████ ██████████ ████████████████████
Loss Vehicle	2012 Toyota Yaris L Automatic
Loss Incident Date	02/01/2024
Claim Reported	02/07/2024

The CCC ONE® Market Valuation Report reflects CCC Intelligent Solutions Inc.'s opinion as to the value of the loss vehicle, based on information provided to CCC by ROOT INSURANCE COMPANY.

Loss vehicle has 40% fewer than average mileage of 137,800.

INSURANCE INFORMATION

Report Reference Number	██████████
Claim Reference	██████████
Adjuster	Behara, Shelli
Appraiser	Snapshot, Inc
Odometer	82,000
Last Updated	02/07/2024 09:06 AM

VALUATION SUMMARY

Base Vehicle Value	\$ 8,357.00
Adjusted Vehicle Value	\$ 8,357.00
Value before Deductible	\$ 8,357.00
Deductible*	-\$ 1,000.00
Total	\$ 7,357.00

BASE VEHICLE VALUE

This is derived per our Valuation methodology described on the next page.

ADJUSTED VEHICLE VALUE

This is determined by adjusting the Base Vehicle Value to account for the actual condition of the loss vehicle and certain other reported attributes, if any, such as refurbishments and after factory equipment.

Adjustments indicated with an Asterisk (*) have been determined by ROOT INSURANCE COMPANY and have been added here for convenience.

The total may not represent the total of the settlement as other factors (e.g. license and fees) may need to be taken into account.

Inside the Report

Valuation Methodology.....	2
Vehicle Information.....	3
Vehicle Condition.....	6
Comparable Vehicles.....	7
Valuation Notes.....	10
Supplemental Information.....	11



VALUATION METHODOLOGY

How was the valuation determined?



CLAIM INSPECTION

ROOT INSURANCE COMPANY has provided CCC with the zip code where the loss vehicle is garaged, loss vehicle VIN, mileage, equipment, as well as loss vehicle condition, which is used to assist in determining the value of the loss vehicle.

DATABASE REVIEW

CCC maintains an extensive database of vehicles that currently are or recently were available for sale in the U.S. This database includes vehicles that CCC employees have physically inspected, as well as vehicles advertised for sale by dealerships or private parties. All of these sources are updated regularly.

SEARCH FOR COMPARABLES

When a valuation is created the database is searched and comparable vehicles in the area are selected. The zip code where the loss vehicle is garaged determines the starting point for the search. Comparable vehicles are similar to the loss vehicle based on relevant factors.

CALCULATE BASE VEHICLE VALUE

Adjustments to the price of the selected comparable vehicles are made to reflect differences in vehicle attributes, including mileage and options. Dollar adjustments are based upon market research.

Finally, the Base Vehicle Value is the weighted average of the adjusted values of the comparable vehicles based on the following factors:

- Source of the data (such as inspected versus advertised)
- Similarity (such as equipment, mileage, and year)
- Proximity to the loss vehicle's primary garage location
- Recency of information



 VEHICLE INFORMATION

VEHICLE DETAILS

Location	
VIN	
Year	2012
Make	Toyota
Model	Yaris
Trim	L
Body Style	Automatic
Body Type	Hatchback
Engine -	
Cylinders	4
Displacement	1.5L
Fuel Type	Gasoline
Carburation	Electronic Fuel Injection
Transmission	Automatic Transmission Overdrive
Curb Weight	2315 lbs

Vehicles sold in the United States are required to have a manufacturer assigned Vehicle Identification Number(VIN). This number provides certain specifications of the vehicle.

Please review the information in the Vehicle Information Section to confirm the reported mileage and to verify that the information accurately reflects the options, additional equipment or other aspects of the loss vehicle that may impact the value.



VEHICLE INFORMATION

VEHICLE EQUIPMENT

Odometer	82,000	
Transmission	Automatic Transmission	✓
	Overdrive	✓
Power	Power Steering	✓
	Power Brakes	✓
	Power Locks	✓
Decor/Convenience	Air Conditioning	✓
	Tilt Wheel	✓
	Rear Defogger	✓
	Intermittent Wipers	✓
	Message Center	✓
Seating	Cloth Seats	✓
	Bucket Seats	✓
	Reclining/Lounge Seats	📄
Radio	AM Radio	✓
	FM Radio	✓
	Stereo	✓
	Search/Seek	✓
	CD Player	✓
	Auxiliary Audio Connection	✓
	Wheel Covers	✓
Safety/Brakes	Air Bag (Driver Only)	✓
	Passenger Air Bag	✓
	Anti-lock Brakes (4)	✓
	Front Side Impact Air Bags	✓
	Head/Curtain Air Bags	✓
	Traction Control	✓
	Stability Control	✓
	Exterior/Paint/Glass	Dual Mirrors
Tinted Glass		✓
Rear Window Wiper		✓
Clearcoat Paint		✓

To the left is the equipment of the loss vehicle that ROOT INSURANCE COMPANY provided to CCC.


✓ **Standard** This equipment is included in the base configuration of the vehicle at time of purchase.


📄 **Additional** Equipment that is not Standard but was noted to be on the loss vehicle.



 VEHICLE INFORMATION

VEHICLE EQUIPMENT

	Metallic Paint	
Other - Cars	California Emissions	





 VEHICLE CONDITION

COMPONENT CONDITION

	Condition	Inspection Notes	Value Impact
INTERIOR			
Seats	AVERAGE PRIVATE	Average wear, no full access	\$ 0
Carpets	AVERAGE PRIVATE	Average wear, no full access	\$ 0
Glass	AVERAGE PRIVATE	Damaged in loss, no heavy pitting seen	\$ 0
Dashboard	AVERAGE PRIVATE	Average wear	\$ 0
Headliner	AVERAGE PRIVATE	No access	\$ 0
EXTERIOR			
Sheet Metal	AVERAGE PRIVATE	The body has no significant surface rust, unaffected panels aligned.	\$ 0
Paint	AVERAGE PRIVATE	The paint has no significant peeling/flaking/fading.	\$ 0
Trim	AVERAGE PRIVATE	Trim in line w/ vehicle age	\$ 0
MECHANICAL			
Engine	AVERAGE PRIVATE	No access	\$ 0
Transmission	AVERAGE PRIVATE	No access	\$ 0
Tires	AVERAGE PRIVATE	No access	\$ 0
Total Condition Adjustments			\$ 0

ROOT INSURANCE COMPANY uses condition inspection guidelines to determine the condition of key components of the loss vehicle prior to the loss. The guidelines describe physical characteristics for these key components, for the condition selected based upon age. Inspection Notes reflect observations from the appraiser regarding the loss vehicle's condition.

CCC makes dollar adjustments that reflect the impact the reported condition has on the value of the loss vehicle as compared to Average Private condition. These dollar adjustments are based upon interviews with dealerships across the United States.

COMPARABLE VEHICLES

Options	Loss Vehicle	Comp 1	Comp 2	Comp 3
Odometer	82,000	117,694	104,265	85,857
Automatic Transmission	✓	✓	✓	✓
Overdrive	✓	✓	✓	✓
Power Steering	✓	✓	✓	✓
Power Brakes	✓	✓	✓	✓
Power Windows	✗	✓	✓	✓
Power Locks	✓	✓	✓	✓
Power Mirrors	✗	✓	✓	✓
Air Conditioning	✓	✓	✓	✓
Tilt Wheel	✓	✓	✓	✓
Cruise Control	✗	✓	✓	✓
Rear Defogger	✓	✓	✓	✓
Intermittent Wipers	✓	✓	✓	✓
Keyless Entry	✗	✓	✓	✓
Message Center	✓	✓	✓	✓
Cloth Seats	✓	✓	✓	✓
Bucket Seats	✓	✓	✓	✓
Reclining/Lounge Seats	✓	✗	✗	✗
AM Radio	✓	✓	✓	✓
FM Radio	✓	✓	✓	✓
Stereo	✓	✓	✓	✓
Search/Seek	✓	✓	✓	✓
CD Player	✓	✓	✓	✓
Steering Wheel Touch Controls	✗	✓	✓	✓
Auxiliary Audio Connection	✓	✓	✓	✓
Satellite Radio	✗	✓	✓	✓
Styled Steel Wheels	✗	✓	✗	✗
Wheel Covers	✓	✗	✓	✗
Aluminum/Alloy Wheels	✗	✗	✗	✓
Drivers Side Air Bag	✓	✓	✓	✓
Passenger Air Bag	✓	✓	✓	✓
Anti-lock Brakes (4)	✓	✓	✓	✓
4-wheel Disc Brakes	✗	✗	✗	✓
Front Side Impact Air Bags	✓	✓	✓	✓
Head/Curtain Air Bags	✓	✓	✓	✓
Hands Free	✗	✓	✓	✓
Traction Control	✓	✓	✓	✓
Stability Control	✓	✓	✓	✓
Dual Mirrors	✓	✓	✓	✓
Body Side Moldings	✗	✗	✗	✓

[REDACTED]

Comp 1 Updated Date: 12/05/2023
 2012 Toyota Yaris Le Automatic 4 1.5l
 Gasoline Electronic Fuel Injection
 VIN [REDACTED]
 Dealership [REDACTED]
 Telephone [REDACTED]
 Source Dealer Ad
 Stock # V6
 Distance from Texarkana, AR
 105 Miles - Tyler, TX

Comp 2 Updated Date: 12/24/2023
 2012 Toyota Yaris Le Automatic 4 1.5l
 Gasoline Electronic Fuel Injection
 VIN [REDACTED]
 Dealership [REDACTED]
 Telephone [REDACTED]
 Source Dealer Ad
 Distance from Texarkana, AR
 160 Miles - Dallas, TX

Comp 3 Updated Date: 12/15/2023
 2012 Toyota Yaris Se Automatic 4 1.5l
 Gasoline Electronic Fuel Injection
 VIN [REDACTED]
 Dealership [REDACTED]
 Source Autotrader
 Stock # CD505457
 Distance from Texarkana, AR
 169 Miles - Carrollton, TX

Comparable vehicles used in the determination of the Base Vehicle Value are not intended to be replacement vehicles but are reflective of the market value, and may no longer be available for sale.


List Price is the sticker price of an inspected dealer vehicle and the advertised price for the advertised vehicle.

Distance is based upon a straight line between loss and comparable vehicle locations.

¹The **Condition Adjustment** sets that comparable vehicle to Average Private condition, which the loss vehicle is also compared to in the Vehicle Condition section.

 **COMPARABLE VEHICLES**

Options	Loss Vehicle	Comp 1	Comp 2	Comp 3
Tinted Glass	✓	✓	✓	✓
Fog Lamps	✗	✗	✗	✓
Rear Spoiler	✗	✗	✗	✓
Rear Window Wiper	✓	✓	✓	✓
Clearcoat Paint	✓	✓	✓	✓
Metallic Paint	✓	✓	✓	✗
California Emissions	✓	✓	✓	✓
List Price		\$ 7,999	\$ 9,995	\$ 8,998
Adjustments:				
Make/Model/Trim		- \$ 150	- \$ 150	- \$ 500
Options		- \$ 66	- \$ 66	
Mileage		+ \$ 939	+ \$ 498	+ \$ 79
Condition ¹		- \$ 1,203	- \$ 1,203	- \$ 1,203
Adjusted Comparable Value		\$ 7,519	\$ 9,074	\$ 7,374



 COMPARABLE VEHICLES

 ADDITIONAL COMPARABLE VEHICLES

Source	Vehicle	Price	Adjusted Comparable Value
Comp 4 Source: Inspected Inventory [Redacted] Monroe, LA [Redacted] 126 Miles From Texarkana, AR	2012 Toyota Yaris Automatic (fleet) 4 1.5I Gasoline Electronic Fuel Injection Odometer: 89,978 VIN: [Redacted] Stock #: VIN9806 Updated Date: 01/03/2024	\$ 10,995 (Take)	\$ 9,461
Comp 5 Source: Autotrader Freeman [Redacted] Grapevine, TX [Redacted] 181 Miles From Texarkana, AR	2012 Toyota Yaris Le Automatic 4 1.5I Gasoline Electronic Fuel Injection Odometer: 119,131 VIN: [Redacted] Stock #: 46506A Updated Date: 01/03/2024	\$ 7,777 (List)	\$ 7,354
Comp 6 Source: Autotrader [Redacted] Lake Charles, LA [Redacted] 226 Miles From Texarkana, AR	2012 Toyota Yaris L Automatic 4 1.5I Gasoline Electronic Fuel Injection Odometer: 74,906 VIN: [Redacted] Stock #: N23951 Updated Date: 12/24/2023	\$ 8,995 (List)	\$ 7,648
Comp 7 Source: Dealer Ad [Redacted] Neosho, MO [Redacted] 238 Miles From Texarkana, AR	2012 Toyota Yaris Le Automatic 4 1.5I Gasoline Electronic Fuel Injection Odometer: 116,537 VIN: [Redacted] Updated Date: 01/22/2024	\$ 7,995 (List)	\$ 7,547

Additional Comparable Vehicles are in summary format, but are adjusted the same as those on the previous page.

Comparable vehicles used in the determination of the Base Vehicle Value are not intended to be replacement vehicles but are reflective of the market value, and may no longer be available for sale.

List Price is the sticker price of an inspected dealer vehicle and the advertised price for the advertised vehicle.

Take Price is the amount that the dealership will accept to sell the inspected vehicle, though a lower price may be obtainable through negotiation.

Distance is based upon a straight line between loss and comparable vehicle locations.



 VALUATION NOTES

This Market Valuation Report has been prepared exclusively for use by ROOT INSURANCE COMPANY, and no other person or entity is entitled to or should rely upon this Market Valuation Report and/or any of its contents. CCC is one source of vehicle valuations, and there are other valuation sources available.

Regulations concerning vehicle value include Arkansas Insurance Department Rule 43.

SUPPLEMENTAL INFORMATION



NHTSA VEHICLE RECALL

NHTSA Campaign ID : 13V292000

Mfg's Report Date : JUL 03, 2013

Component : STEERING

Potential Number Of Units Affected : 74

Summary : Toyota is recalling certain model year 2012 Yaris vehicles manufactured August 21, 2011, through August 31, 2011. A relay in the Power Steering Control Module of the electronic power steering system could experience a short circuit due to insufficient distance between terminals in the relay and moisture contamination of relay coil windings. A short circuit in the relay could disable power steering assistance.

Consequence : If the power steering assistance shuts off, the driver may have difficulty steering the vehicle at low speeds, increasing the risk of a crash.

Remedy : Toyota will notify owners, and dealers will replace the power steering control module. The recall began on July 31, 2013. Owners may contact Toyota at 1-800-331-4331.

Notes : Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 or go to www.safercar.gov.

NHTSA Campaign ID : 15V134000

Mfg's Report Date : MAR 09, 2015

Component : STRUCTURE

Potential Number Of Units Affected : 16,582

Summary : Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain model year 2012-2015 Yaris vehicles manufactured August 31, 2011, to February 9, 2015, and sold in Puerto Rico. The affected vehicles may have been manufactured with a roof headliner that does not provide the proper occupant protection in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 201, "Occupant Protection in Interior Impact."

Consequence : If the vehicles are equipped with a headliner that does not meet the impact requirements, there is an increased risk of occupant injury in the event of a crash.

Remedy : Toyota will notify owners, and dealers will replace the headliner, free of charge. The recall is expected to begin in mid-April 2015. Owners may contact Toyota customer service at 1-800-331-4331.

Notes : Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA Campaign ID : 17V006000

Mfg's Report Date : January 9, 2017

The National Highway Traffic Safety Administration has issued 5 safety related recall notices that may apply to the above valued vehicle.

SUPPLEMENTAL INFORMATION

Component : AIR BAGS

Potential Number Of Units Affected : 567,911

Summary : Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2012 Toyota 4Runner, Corolla, Corolla Matrix, Sienna, Yaris, Scion xB, Lexus ES350, GX460, IS-F, IS250, IS350, IS250C, IS350C, and Lexus LFA vehicles originally sold, or ever registered, in Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands, or "Zone A." Additionally, unless included in "Zone A" above, Toyota is recalling certain 2009 Toyota Corolla, Corolla Matrix, Yaris, Yaris HB, Scion xB, Pontiac Vibe, Lexus, ES350, IS250, IS350, and IS-F vehicles originally sold, or ever registered, in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia, or "Zone B." Additionally, unless included in "...

Consequence : An inflator rupture may result in metal fragments striking the vehicle occupants resulting in serious injury or death.

Remedy : Toyota will notify the Toyota, Scion and Lexus owners. General Motors will contact the Pontiac owners. Depending on the model, dealers will replace the passenger frontal air bag inflator or the air bag assembly, free of charge. Interim letters informing owners that parts are not yet available are expected to begin January 30, 2017. Owners will receive a second notice when remedy parts become available. Owners may contact Toyota customer service at 1-800-331-4331, or Pontiac customer service at 1-800-762-2737. Toyota's numbers for interim notification for this campaign are G1P (Toyota Zone A), G1R (Toyota Zone B), H1A (Toyota Zone C), G2G (Lexus Zone A), G2H (Lexus Zone B) and H2A (Lexus Zone C). Toyota's numbers for final remedy for this campaign are G0P (Toyota Zone A), G0R (Toyota Zone B), H0A (Toyota Zone C), GLG (Lexus Zone A), GLH (Lexus Zone B) and HLA (Lexus Zone C).

NHTSA Campaign ID : 18V025000

Mfg's Report Date : January 9, 2018

Potential Number Of Units Affected : 14,585

Summary : Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2010-2012 Yaris vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B." Additionally, these vehicles are also being recalled in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming, or "Zone C." These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation ...

Consequence : An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death.

SUPPLEMENTAL INFORMATION

Remedy : Toyota will notify owners, and dealers will replace the passenger frontal air bag assemblies, free of charge. The recall is expected to begin by March 10, 2018. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are G0R (Zone B), and H0A (Zone C).

NHTSA Campaign ID : 19V741000

Mfg's Report Date : October 17, 2019

Potential Number Of Units Affected : 928,203

Summary : Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2010-2016 4Runner, 2003-2006 Tundra, 2003-2013 Corolla, 2009-2010 Corolla Matrix, 2004-2005 RAV4, 2002-2007 Sequoia, 2011-2013 Sienna, 2008-2012 Scion xB, 2008-2009 Lexus IS-F, 2007-2012 Yaris and Lexus ES350, 2010-2017 Lexus GX460, 2002-2010 Lexus SC430, 2006-2012 Lexus IS250 and IS350 and 2010-2015 Lexus IS250C and IS350C vehicles. These vehicles had their driver or passenger frontal air bag inflators previously replaced under a prior recall using inflators of the same design. The inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy : Toyota will notify owners. Depending on the vehicle model, dealers will replace the driver or front passenger air bag inflator or the air bag assembly using an alternate inflator , free of charge. The recall is expected to begin November 15, 2019. Owners may contact Toyota customer service at 1-888-270-9371 or Lexus customer service at 1-800-255-3987. Toyota's numbers for this recall are J0A, J0B, and J0C. Lexus' numbers for this recall are JLI, JLJ, and JLK.